

# Oil Field Environmental Incident Summary

**Incident:** 20131231121750      **Date/Time of Notice:** 12/31/2013 12:00

**Responsible Party:** Continental Resources, Inc.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** FASCHING 1-22H

**Field Name:** HEBRON

**Well File #:** 18964

**Date Incident:** 12/30/2013      **Time Incident:** 08:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 104

**Sec:** 22

**Qtr:**

**Location Description:**

**Submitted By:** Justin Collins

**Received By:**

**Contact Person:** Justin Collins  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	<b>3</b>	<b>barrels</b>	<b>3</b>	<b>barrels</b>		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

***Potential Environmental Impacts:***

Well site soil

***Action Taken or Planned:***

Valve was replaced with spring loaded valve, fluid was sucked up. Contaminated material will be removed.

***Wastes Disposal Location:*** Unknown at time of reporting.

***Agencies Involved:***

***Updates***

---

***Date:*** 12/31/2013 ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill remained on location. NDIC retains oversight.